

## Transponder position

Transponders transmit their signal like a torch beam, out of the orange part.

The transponder should be pointing down towards the track, in the 'H' of the forks.

